PHOTOGRAPHIC INTERPRETATION



Declass Review, NIMA/DoD

SELECTED TRANSPORTATION AND INFILTRATION ACTIVITY SOUTHEAST ASIA

25X1

NPIC/R-210/66 **JULY 1966**

SUMMARY NO 10

Approved For Release 2003/05/15 : CIA-RDP78B04560A005500010024-2

WARNING

This document contains information affecting the national defense of the United States, within the meaning of Title 18, sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law.

BEY1

Approved For Release 2003/05/15 : CIA-RDP78B04560A005500010024-2

Next 1 Page(s) In Document Exempt

PREFACE

This report is a summary of selected information on transportation and infiltration activity in Southeast Asia, primarily the Laotian Panhandle, as reported by NPIC during the period indicated on the cover. For a comprehensive study of road development in this area prior to 1 April 1966 see NPIC R-110/66, Communist Road Net Development in the Laotian Panhandle (CONFIDENTIAL/


Items are numbered and arranged according to location from north to south. Annotated maps of varying scales have been included to assist the reader in locating the items. Each large-scale map depicts all motorable roads photographically confirmed by NPIC.


Missions, mission dates, frames, and NPIC cable and briefing board references are listed after each item, as appropriate.

25X1C

CONTENTS


- 1. Dual-gauge Capability, Ha Noi/Ping Hsiang Rail Line
- 2. New By-pass Road and Probable Ferry Crossing
- 3. Probable Truck Park on Route 137
- 4. Road Interdictions, Route 92
- 5. Landslides on Route 96
- 6. Route 110 Segment Remains Unserviceable






	R-210/66	
	25X1C R-210/00	
	1. Dual-gauge Capability, Ha Noi/Ping Hsiang Rail Line	
	A dual-gauge rail line capability (Figure 1B) presently exists on the Ha Noi/Ping Hsiang Rail Line between Cao Nung Railroad Bridge at 21-33N 106-29E and Kep Rail Yard at 21-25N 106-17E. Meter gauge rail lines may be converted to dual-gauge by widening the rail bed and adding a third rail,	7
	permitting utilization of the line by both meter gauge (used in North Vietnam) and standard gauge (used in China) rail cars. The existence of a third rail between the Cao Nung Railroad Bridge and China has not been verified due to a lack of photographic coverage.	•
25X1D	On photography of the dual-gauge rail line was not observed 4.5 nm northeast of Kep at 21-26N 106-21E; however, there was evidence of construction preparation for the addition of a third rail. The rail bed had been widened and improved and standard gauge rail ties had been substituted for the shorter rail ties used for meter gauge lines (Figure 1C). The third rail was in place 9.5 nm northeast of Kep at	
	21-30N 106-25E	25X1D
	Construction activity observed south of Kep indicates the probable extension of the dual-gauge capability to Ha Noi. A work train discharging ballast was observed at 21-19N 106-15E (Figure 1E) and standard gauge rail ties were observed at 21-16N 106-10E (Figure 1F) and at 21-20N 106-15E. Undistributed ballast has been observed piled at numerous places in this area.	
	A rail line is under construction between Kep and the Thai Nguyen Ore Processing Plant rail line (Figure 1A). The junction of this line with the Ha Noi/Ping Hsiang Rail Line at 21-25N 106-18E (Figure 1D) was observed on photography and only standard gauge track was observed in this area.	25)
		- : :
		•

6



25X1C x=21.0/65



25X1D


FIGURE 1.A. STANDARD GAUGE RAIL LINE UNDER CONSTRUCTION, NORTH VIETNAM

25X1

Page 8

Approved For Release 2003/05/25/10 LANDH ASB04560A005500010024-2

Richard Francisco




25X1D

25X1

FIGURE 1B. DUAL-GAUGE RAIL LINE, NORTH VIETNAM

25X1C


3-21044



25X1D FIGURE 1C. DUAL-GAUGE RAIL LINE UNDER CONSTRUCTION, NORTH VIETNAM

Page 10


25X1C R=210/66



25X1D

FIGURE 1D. DUAL-GAUGE RAIL LINE, NORTH VIETNAM

Page 11




25X1D

25X1

FIGURE 1E. PROBABLE DUAL-GAUGE RAIL LINE UNDER CONSTRUCTION, NORTH VIETNAM

E-210/66



25X1D


FIGURE 1F. PROBABLE DUAL-GAUGE RAIL LINE UNDER CONSTRUCTION, NORTH VIETNAM

Page 13

2. New By-pass Road and Probable Ferry Crossing


A new by-pass road extends from Route 137 at UTM KE368454 southwest to a new probable ferry crossing on the Song Troc (river: at UIM XE361447 (Figure 2). From this point the road continues generally west, then northnortheast along the base of a large karst hill, to join Route 101 at UTM XE36(495. Numerous truck pull-offs are observed, through scattered clouds. at UTM XE348463.


The Route 101 ferry crossing at 17-36N 106-18E is unserviceable due to numerous road interdictions on both sides of the river. All vehicular traffic appears to be continuing southwest along the rew road. The ferry boats previously reported in this area are not observed.



3. Probable Truck Park on Route 137

A probable truck park is observed on Route 137 at UTM XE311.265. Part of a complex road network is observed 500 feet south of the road in a beavily forested area. No associated facilities are a served; however. the dense tree canopy limits interpretation.





Appro 25 16 Release 300 15 16 16 Release 300 10024-2

R-210/66

4. Road Interdictions, Route 92

25X1D

Numerous interdictions are observed on Route 92 immediately east of its junction with Routes 914 and 920 at UTM XD592181 (Figure 3). There is no evidence of recent vehicular activity in this area. South of this point, Route 92 deteriorates severely as a result of additional interdictions, heavy rain, and the lack of normal road maintenance.

ROUTE 92 ROUTE 911

FIGURE 3. ROAD INTERDICTIONS, ROUTE 92/914/920 JUNCTION, LAOS




25X1C Approved For Release 20 (2014) FMT-FALP 78B04560A005500010024-2

R-210/66

5. Landslides on Route 96


Route 96 is unserviceable at 15-25N 107-00E. Landslides have rendered approximately 350 yards of the road, from UTM YC149062 to 149065 (Figure 4), impassable for vehicular traffic; however, a well-used foot trail extends along the road alignment. Weathering has caused the road embankment to collapse at UTM YC147069, rendering that point of the road also impassable.

25X1D



25X1D


FIGURE 4. LANDSLIDES, ROUTE 96, LAOS



6. Route 110 Segment Remains Unserviceable

Successive photographic coverage indicates that Route 110 remained unserviceable from due to concentrated interdictions at UTM YB447289. There has been no attempt to repair or by-pass the interdictions. No vehicles have transited the area during this period; however, a foot trail is observed (Figure 5).

25X1D



25X1D FIGURE 5. ROAD INTERDICTIONS, ROUTE 110, LAOS

Approved For Release 2003/05/15: CIA-RDP78B04560A005500010024-2

25X1

25X1

25X1D

